

## Building Safety Certificate



This is to certify that I have inspected the school building of Shantiniketan School an institute of M/S. KPR Memorial Educational Academy, situated at 35-35, GK Colony, RK Puram, Neredmet, Sainikpuri, Secunderabad dated 21<sup>st</sup> September 2020.

The building consists of Ground + 2 floors. RCC framed structure consists of RCC footings, Columns Plinth Beams, Lintel Beams covered by RCC Slab and Beams, full height brick walls all around and partitions with aluminium glazed windows. The building is designed as per I.S. Codes and materials used of good quality. We examined the various parts of the building. I am of the opinion that the building is structurally sound and the stability will not be endangered by their use, no adverse indication about the structural weakness or impairment in the building. Hence, certified that the building is structurally sound and stable.

*Chandra*  
29/9/2020  
Superintending Engineer  
(R&B) Rural Region,  
Balkampet, Hyderabad.